


NOTES:

1. DETAIL TO BE USE IN CONJUNCTION WITH SOPREMA GENERAL REQUIREMENTS, APPLICATION METHODS AND APPROVED DETAILS.
2. SOPREMA WARRANTS ADHESION TO EXISTING SOPREMA FIELD CAP MEMBRANE PLY WHEN SOPRAWALK IS FULLY HEAT WELDED OR ADHERED WITH 2-PART MEMBRANE ADHESIVE (REMOVE PLASTIC FILM IF PRESENT) EMBED GRANULES MIN. 6" (152mm) AROUND EXISTING CAP SHEET EDGES AND PRIME INNER AREAS BEFORE HEAT WELDING SOPRAWALK.
3. SOPREMA ADHESIVES, CEMENTS, MASTICS, PRIMERS AND SEALANTS ARE REQUIRED WHERE INDICATED.
4. SOPREMA DOES NOT WARRANT ADHESION TO EXISTING SOPREMA FIELD CAP MEMBRANE PLY WHEN OTHER ADHESIVE METHODS ARE USED.

		310 QUADRAL DRIVE WADSWORTH, OHIO 44281 (330) 334-0066	
		TITLE SOPRAWALK PROTECTION MEMBRANE	
SCALE	DWN	CHK	APPROVAL DATE
NONE	DMT	PR	9/01/05
DRAWING NUMBER			REV
MISC-005			0

** USAGE OF THIS DRAWING IS GOVERNED BY THE TERMS OF SERVICE FOR SOPREMA DETAIL. PLEASE CONSULT THESE TERMS OF SERVICE PRIOR TO UTILIZING THIS DRAWING.