


NOTES:

1. DETAIL TO BE USE IN CONJUNCTION WITH SOPREMA GENERAL REQUIREMENTS, APPLICATION METHODS AND APPROVED DETAILS.
2. SOPREMA ADHESIVES, CEMENTS, MASTICS, PRIMERS AND SEALANTS ARE REQUIRED WHERE INDICATED.
3. WHEN A TWO-PLY FLASHING SYSTEM IS SPECIFIED, EXTEND DOWN AND LAP OVER FLASHING PLY FASTENERS. THE HIGH WALL MEMBRANE COVER PLY IS HEAT WELDED. DO NOT BOND SELF-ADHESIVE MEMBRANES TO CMU SURFACES.

		310 QUADRAL DRIVE WADSWORTH, OHIO 44281 (330) 334-0066	
		TITLE Overflow Through-Wall Scupper Cross Sec.	
SCALE	DWN	CHK	APPROVAL DATE
NONE	DMT	PR	9/1/05
DRAWING NUMBER			REV
AWBF-010			0

** USAGE OF THIS DRAWING IS GOVERNED BY THE TERMS OF SERVICE FOR SOPREMA DETAIL. PLEASE CONSULT THESE TERMS OF SERVICE PRIOR TO UTILIZING THIS DRAWING.